

United States Steel Corporation Clainton Works 400 State Street Clainton, PA 15025

RECEIVED

May 6, 2010

MAY 1 8 2010

3AP20

Mr. Ed Peresie
Department of Air Quality
Bureau of Air Pollution Control
301 Thirty-Ninth Street
Pittsburgh, PA 15201

U.S. Environmental Protection Agency Region III Air, Radiation & Toxics Division 1650 Arch Street Philadelphia, PA 19103-2029 ATTN: James W. Hagedorn

Assistant Council
Department of Environmental Protection
Southwest Region
400 Waterfront Drive
Pittsburgh, PA 15222-4745
ATTN: Steve Hepler

Department of Justice Environmental and Natural Resource Division Environmental Enforcement Section P.O. Box 7611 Ben Franklin Station Washington, D.C. 20044 ATTN: David Street, Esq.

Subject: USS Reference Number: 10-0212

ACHD Reference Number: N/A #20 Battery Igniter Flare

USS Clairton Works

Gentlemen:

The attached form confirms our verbal report of the outage. Any questions concerning this matter should be referred to Coleen M. Davis at 412-233-1015.

Sincerely,

Mark G. Tabler Plant Manager Clairton Works

NOTICE OF OUTAGE OF EQUIPMENT ARTICLE XXI - SECTION 2108.1

- USS Reference Number: 1. 10-0212 ACHD Reference Number: N/A
- Date & Time of Breakdown: Date: 05/05/10 Time: 2010 hours 2.
- Company Name: U.S. Steel Corporation USS Clairton Works 3.
- Specific Equipment Involved or Affected: #20 Battery Igniter 4. Flare
- BAPC Permit Number (if applicable): 5.
- 6. Location: Clairton, PA
- Nature and cause of breakdown: The #20 Battery Igniter Flare was 7. unavailable for service due to an extinguished pilot light.
- 8. Identification of Emissions:
 - Type(s) (CO, NOX, SO2, Particulates, Hydrocarbons, etc.) A. No environmental impact.
 - Toxic qualities of each type (including its qualities as an B. irritant, and its potential for causing illness, disability, or mortality). N/A

___ Date_5/6/10

- Amount of each type emitted (or likely to be emitted). C. N/A
- Measures taken (or to be taken) to minimize length of breakdown 9. and amount of emissions, including shutdown or curtailment (or why it is impossible or impractical to do so). The pilot was lit and the igniter flare was available for service.

Facility back in operation - Date: 05/05/10 Time: 2230 hours 10.

Signature 11-7

Bryan M. Kresak

Environmental Control Engineer Phone: 412-233-1468